



AA: General

Date:	21-03/12	Vessel:		Mermaid Sapphire					
Time	Wind direction	Wind Speed (Kts.)	Visibility (NM)	Pressure (mbar)	Current speed (Kts.)	Current Direction	Weather	Cloud (Octas)	Swell Height (m)
0600	NNE	11	10+	1011	-	-	Fine	4/8	2.0
1200	N	12	10+	1012	-	-	Fine	5/8	2.0
1800	NNE	10	10+	1011	-	-	Fine	3/8	2.0
2400	E	20	6	1010	-	-	Squalls	6/8	2.5
POB:	60								

BB: Activity

Activity at 2400Hrs:

Position 11 20'N 142 12'E	Field/Port detail:
Activity: V/I in ADP at Challenger Deep	
Project No: 11049	Estimate Date/Time of Completion:
Project Name:	

Time:	Activity:
0001	V/I standing by at Challenger Deep waiting for daylight to assess weather conditions. Fire and security rounds made frequently. Routine maintenance ongoing. V/I moving easily to rough seas and moderate swell
2400	V/I in DP at Challenger Deep, preparing for transit to Ulithi Atoll. V/I moving easily to moderate seas and swell



	Water (m/3)	Fuel (m/3)	Lub Oil (Ltrs)
Previous day	244.7	401.9	10283
Consumed	20.3	10.5	-
Loaded / Made	17	-	-
Discharged	-	-	-
ROB	241.4	391.4	10283

CC: Transit

Latitude. (N / S)	Longitude. (E / W)	Destination.	Distance Steamed Last 24Hrs.	Average Speed Last 24Hrs.	General Average Speed.	Distance to go.	ETA. @11.0kts
							-

DD: Waiting on weather

Duration:	
Expected improvement:	
Details:	

EE: Vessel breakdown or vessel is out of commission due to maintenance or contract preparation

Reason:	
Duration:	

FF: Incidents, Accidents & Safety Observations:

Accident, Incident, Near Miss & Safety Observation	
Report Number:	
Brief Details:	

Masters Name:

Capt: Stuart Buckle