



AA: General

Date:	24/3/12	Vessel:		Mermaid Sapphire					
Time	Wind direction	Wind Speed (Kts.)	Visibility (NM)	Pressure (mbar)	Current speed (Kts.)	Current Direction	Weather	Cloud (Octas)	Swell Height (m)
0600	NE	10	7	1007	0.5	190	O'cast	8/8	0.5
1200	NE	8	10	1009	0.3	140	Sunny	6/8	0.5
1800	ENE	14	10	1009	0.5	070	Cloudy	6/8	1.3
2400	ENE	16	7	1010	0.5	082	Fainy	8/8	2.0
POB:	60								

BB: Activity

Activity at 2400Hrs:

Position 10 53.66' N 141 25.26' E	Field/Port detail:
Activity: V/I in transit to Challenger Deep	

Project No: 11049

Estimate Date/Time of Completion:

Project Name:

Time:	Activity:
0001	V/I in DP South West of Falalop Island, routine maintenance and pre dive checks being carried out Deep Sea Challenger. Regular fire and security rounds made regularly. All
0015	2 pax return onboard from Barakuda
1200	GPS Position: 10 00' N 139 47' E
1220	Last R.I. Bonboard, securing crane and items on deck for sea passage to Challenger Deep.
1238	Vessel off DP and depart from Ulithi Atoll to Challenger Deep.
2400	V/I on passage to Challenger Deep. Regular fire and security rounds made regularly. All company and local regulations observed.

	Water (m/3)	Fuel (m/3)	Lub Oil (Ltrs)
Previous day	260	369.2	10214
Consumed	8.6	10.5	130
Loaded / Made	17	-	-
Discharged	-	-	-
ROB	268.4	358.7	10084



CC: Transit

Latitude. (N / S)	Longitude. (E / W)	Destination.	Distance Steamed Last 24Hrs.	Average Speed Last 24Hrs.	General Average Speed.	Distance to go.	ETA. @10.0kts
10 53.6N	141 25.3'E	Challenger Deep	118	10.38	10.38	52.6	0516

DD: Waiting on weather

Duration:	
Expected improvement:	
Details:	

EE: Vessel breakdown or vessel is out of commission due to maintenance or contract preparation

Reason:	
Duration:	

FF: Incidents, Accidents & Safety Observations:

Accident, Incident, Near Miss & Safety Observation	
Report Number:	
Brief Details:	

Masters Name:

Capt: Stuart Buckle