



AA: General

Date:	26/3/12	Vessel:		Mermaid Sapphire					
Time	Wind direction	Wind Speed (Kts.)	Visibility (NM)	Pressure (mbar)	Current speed (Kts.)	Current Direction	Weather	Cloud (Octas)	Swell Height (m)
0600	NE	14	12	1010	0.9	099	Partly cloudy	4/8	1.5
1200	NE	10	12	1011	0.8	048	Partly cloudy	5/8	1.5
1800	ENE	18	12	1011	0.9	082	Cloudy	6/8	1.2
2400	ENE	14	12	1011	0.7	093	Partly cloudy	4/8	1.2
POB:	60								

BB: Activity

Activity at 2400Hrs:

Position 10 38.1'N 141 05.9'E	Field/Port detail:
Activity: V/I in transit to Ulithi Atoll	

Project No: 11049

Estimate Date/Time of Completion:

Project Name:

Time:	Activity:
0001	V/I standing by in Dive location, routine maintenance and pre dive checks being carried out Deep Sea Challenger. Regular fire and security rounds made regularly. All company and local regulations observed.
0125	Start all thrusters, V/I in auto DP and Barakuda arrived in dive location.
0130	HIPAP pole down.
0147	Zodiac in the water.
0210	Zodiac back with 3 pax from Barakuda
0317	Drift test, drifted 420mtrs x 279 degrees
0427	Vessel at Dive location.
0450	Submarine off deck.
0454	Submarine in the water and hook released.
0514	Submarine clear surface, 11 22.2'N-142 35.3'E
0517	LTW swing out.
0536	Dunker in the water.
0658	Zodiac back with 1 pax from Barakuda.
0752	Deep Sea Challenger on the bottom.



0948	Deep Sea Challenger on North Slope.
1030	Deep Sea Challenger coming back to surface
1052	HIPAP pole up
1056	LTW secured.
1057	Dunker up.
1200	Deep Sea Challenger on surface.
1210	Vessel on DP joystick mode.
1238	Deep Sea Challenger on deck.
1241	Vessel back to auto DP.
1245	Deep Sea Challenger hatch open.
1251	James Cameron comes out from Deep Sea Challenger.
1355	Prime R.I.B picks up 5 pax to Octopus (James Cameron and wife, Robert Brunnele, Don Walsh and Maria Wilhelm).
1428	Prime R.I.B on deck.
1435	Zodiac brings back 3 pax to Barakuda.
1500	3 pax from Barakuda onboard.
1507	Zodiac onboard and secured, Vessel proceeding to Ulithi Atol.
2400	Vessel in transit to Falalop Island-Ulithi Atol. Regular fire and security rounds made regularly. All company and local regulations observed.

	Water (m/3)	Fuel (m/3)	Lub Oil (Ltrs)
Previous day	277.9	346.0	10084
Consumed	17.7	10.8	-
Loaded / Made		-	-
Discharged		-	-
ROB	260.2	335.2	10084

CC: Transit

Latitude. (N / S)	Longitude. (E / W)	Destination.	Distance Steamed Last 24Hrs.	Average Speed Last 24Hrs.	General Average Speed.	Distance to go.	ETA. @10.0kts

DD: Waiting on weather

Duration:	
Expected	



improvement:	
Details:	

EE: Vessel breakdown or vessel is out of commission due to maintenance or contract preparation

Reason:	
Duration:	

FF: Incidents, Accidents & Safety Observations:

Accident, Incident, Near Miss & Safety Observation	
Report Number:	
Brief Details:	

Masters Name:

Capt: Mike Golding