



AA: General

Date:	27/3/12	Vessel:		Mermaid Sapphire					
Time	Wind direction	Wind Speed (Kts.)	Visibility (NM)	Pressure (mbar)	Current speed (Kts.)	Current Direction	Weather	Cloud (Octas)	Swell Height (m)
0600	NE	12	12	1010	0.8	062	Cloudy	5/8	1.0
1200	ENE	10	12	1011	0.7	058	Cloudy	5/8	0.4
1800	ENE	10	12	1011	0.7	059	O'cast	7/8	0.3
2400	NE	20	12	1012	0.5	060	Cloudy	5/8	1.0
POB:	58								

BB: Activity

Activity at 2400Hrs:

Position 09 58.6'N 139 45.7'E	Field/Port detail:
Activity: V/I standing by in Ulithi Atol	

Project No: 11049

Estimate Date/Time of Completion:

Project Name:

Time:	Activity:
0001	V/I in transit to Ulithi Atol, routine maintenance and pre dive checks being carried out Deep Sea Challenger. Regular fire and security rounds made regularly. All company and local regulations observed.
0945	Vessel starts all thrusters.
1010	Vessel in DP mode.
1022	Rescue Boat in the water.
1030	Launch boat alongside starboard side.
1100	Launch boat departs with 2 Pax National Geographics.
1100	New Chief Officer Dimitry Gress signed on.
1200	Capt. Stuart Buckle signed off. Capt. Mike Golding Assumes Command.
1350	Rescue Boat proceeding to ashore to taking ship foods.
1400	Received ship foods from ashore.
1807	All ship personnel onboard and rescue boat onboard.
1830	Ship crane secured.
1839	Vessel on manoeuvre mode.
2400	Vessel standing by in Falalop Island-Ulithi Atol. Regular fire and security rounds made regularly. All company and local regulations observed.



	Water (m/3)	Fuel (m/3)	Lub Oil (Ltrs)
Previous day	282.7	335.2	10084
Consumed	11.6	12.4	5
Loaded / Made	5.0	-	-
Discharged		-	-
ROB	276.1	322.8	10079

CC: Transit

Latitude. (N / S)	Longitude. (E / W)	Destination.	Distance Steamed Last 24Hrs.	Average Speed Last 24Hrs.	General Average Speed.	Distance to go.	ETA. @10.0kts

DD: Waiting on weather

Duration:	
Expected improvement:	
Details:	

EE: Vessel breakdown or vessel is out of commission due to maintenance or contract preparation

Reason:	
Duration:	

FF: Incidents, Accidents & Safety Observations:

Accident, Incident, Near Miss & Safety Observation	
Report Number:	
Brief Details:	

Masters Name:**Capt: Mike Golding**